S50220Y ATTACHMENT -Page 197 of

SHUTTLE CRITICAL ITEMS LIST - ORBITER

SUBSYSTEM : ACTIVE THERMAL CONTROL FMEA NO 06-30 -0504 -2 REV:03/03/8

: PADIATOR & FLOW CONTROL ASSEMBLY

CRIT. FUNC:

:MC203-0002-0050 P/N RI

CRIT. HDW: 104 103

P/N VENDOR: 224-00050

102 VEHICLE Х х X

QUANTITY : 2 EFFECTIVITY: 00 X D0 X L5 LO PĹ PHASE(S):

:TWO, ONE PER LOOP

REDUNDANCY SCREEN: A-PASS B-FAIL C-PA

PREPARED BY:

APPROVED BY> O. TRAN GAT DES

APPROVED BY, (NASA) : Hallkatige SSM

DES REL

D. RISINGULAREL

REL

QΞ

W. SMITH

TTEM:

VALVE, BYPASS, RADIATOR.

FUNCTION:

PROVIDES COMPLETE BYPASS OF RADIATORS FOR UNDER TEMPERATURE PROTECTION OF THE FREON COOLANT LOOPS TO PREVENT THE FREEZING OF THE CABIN WATER COOLANT LOOPS.

PAILURE MODE:

OPEN (ELECTRICAL), FAILS IN THE RADIATOR FLOW POSITION.

CAUSE(S):

VIBRATION, MECHANICAL SHOCK, CORROSION.

EFFECT(S) ON:

- (A) SUBSYSTEM (B) INTERFACES (C) MISSION (D) CREW/VEHICLE
- (A) LOSS OF ONE REDUNDANT ELECTRICAL DRIVE FOR ONE BYPASS VALVE.
- (B,C,D) NO EFFECT. REDUNDANT ELECTRICAL DRIVE SYSTEM WILL PROVIDE BYS OPERATION.
- (E) FUNCTIONAL CRITICALITY EFFECT LOSS OF ALL RADIATOR UNDER TEMPERA TURE CONTROL/PROTECTION (REDUNDANT MOTOR CONTROL AND ACTUATOR OF THE BYPASS VALVE, AND THE FLOW CONTROL VALVE) CAN FREEZE THE INTERCHANGER AND RESULT IN RUPTURE OF WATER AND FREON COOLANT LOOPS. LOSS OF ALL VEHICLE COOLING WILL CAUSE LOSS OF CREW/VEHICLE. REDUNDANCY SCREEN '! FAILS BECAUSE VALVE IS OPERATED BY SIMULTANEOUS DUAL MOTOR DRIVES AND FAILURE OF ONE MOTOR DRIVE DOES NOT AFFECT VALVE OPERATION.
- DISPOSITION & RATIONALE:
 - (A) DESIGN (B) TEST (C) INSPECTION (D) FAILURE HISTORY (E) OPERATIONAL USE
- (A) DESIGN WELDED CONSTRUCTION WITH BELLOWS FOR DYNAMIC SEALS. DUAL ELECTRICAL CONTROL CIRCUITS. THE FLOW CONTROL ASSEMBLY IS MOUNTED ON VIBRATION ISOLATORS. VALVE HOUSING AND SEAT ARE MADE OF STAINLESS STEEL, WHICH IS COMPATIBLE WITH FREON 21. ELECTRICAL COMPONENTS ARE CONFORMAL COAT AND CORROSION RESISTANT.

SHUTTLE CRITICAL ITEMS LIST - ORBITER

SUBSYSTEM (ACTIVE THERMAL CONTROL FMEA NO 06+30 +0504 +2 REV:03/59/53

(B) TEST

QUALIFICATION TEST - QUALIFICATION TESTED FOR 100 MISSION LIFE. VIBRATION TESTED AT 0.1 G^2/HZ FOR 48 MIN/AXIS, SHOCK TESTED AT +/- 20 G EACH AXIS, AND 3500 CYCLZ VALVE LIFE TEST.

ACCEPTANCE TEST - VALVE FUNCTIONAL TEST IS PERFORMED DURING ATP. AVT IS DONE AT COMPONENT LEVEL AND AT A HIGHER ASSEMBLY (FLOW CONTROL ASSEMBLY) DIELECTRIC STRENGTH TEST WAS PERFORMED AT 1250 VOLTS WITH A LEAKAGE RATE OF LESS THAN 2 ma/Sec.

OMRSD - RADIATOR BYPASS VALVE MANUAL AND AUTO CHECKOUT DURING GROUND TURNAROUND.

(C) INSPECTION

RECEIVING INSPECTION

RAW MATERIAL CERTIFICATIONS ARE VERIFIED BY INSPECTION. PARTS PROTECTION VERIFIED BY INSPECTION.

CONTAMINATION CONTROL

CONTAMINATION CONTROL PROCESSES, CONTAMINATION CONTROL PLAN AND CORROSIC PROTECTION PROVISIONS ARE VERIFIED BY INSPECTION. FLUID SYSTEM SAMPLES FOR CONTAMINATION ARE VERIFIED BY INSPECTION.

ASSEMBLY/INSTALLATION

MANUFACTURING, INSTALLATION, AND ASSEMBLY OPERATIONS ARE VERIFIED BY INSPECTION.

NONDESTRUCTIVE EVALUATION

X-RAY EXAMINATION OF FUSION WELDS IS VERIFIED BY INSPECTION. ULTRASONI: INSPECTION OF RAW MATERIAL VERIFIED BY INSPECTION. DYE PENETRANT EVALUATION OF MACHINED PARTS VERIFIED.

CRITICAL PROCESSES

WELDING IS VERIFIED BY INSPECTION. PASSIVATION, HEAT TREATING AND BRAZING ARE VERIFIED BY INSPECTION.

TESTING .

VIBRATION REQUIREMENT IS VERIFIED BY INSPECTION DURING ATP. LEAKAGE DURING PROOF PRESSURE AND HELIUM LEAK CHECK TESTS IS VERIFIED BY INSPECTION. INSULATION RESISTANCE AND DIELECTRIC STRENGTH REQUIREMENTS ARE VERIFIED BY INSPECTION DURING ATP.

HANDLING/PACKAGING

HANDLING AND STORAGE ENVIRONMENTS ARE VERIFIED BY INSPECTION.

(D) FAILURE HISTORY

NO APPLICABLE FAILURE HISTORY.

(E) OPERATIONAL USE

FIRST FAILURE IS NOT DETECTABLE, REDUNDANT ELECTRICAL CIRCUIT AND MOTOR WILL CONTROL THE BYPASS VALVE FOR NORMAL OPERATION. NO CREW ACTION REQUIRED.

M. 34 M